

**Statewide Compliance Monitoring Report for 2025
Alaska Department of Natural Resources
Division of Forestry & Fire Protection**

Table of Contents	Page
Region I BMP Compliance Ratings and Inspection Totals	1
Region I BMP Compliance Monitoring Summary For 2025	2
Region I Compliance Monitoring Summary For Previous 5 Years	3
Region II BMP Compliance Ratings and Inspection Totals	4
Region II BMP Compliance Monitoring Summary For 2025	5
Region II Compliance Monitoring Summary For Previous 5 Years	6
Region III BMP Compliance Ratings and Inspection Totals	7
Region III BMP Compliance Monitoring Summary For 2025	8
Region III Compliance Monitoring Summary For Previous 5 Years	9



Active state sale, Tok area (T. Chaney)



Active state sale, second growth Tuxekan Island (S. Staunton)



Moving equipment via ramp barge in southeast (P. Palkovic)

FRPA REGION I COMPLIANCE RATING TOTALS

REGION I Totals	2021	2022	2023	2024	2025
#BMPs Rated	660	423	529	587	335
Average Score all BMPs on a 1 to 5 (best) scale	4.5	4.3	4.2	4.3	4.3
#BMPs Rated <4	59	45	61	64	46
% of all BMP's rated <4	9%	11%	11%	11%	14%
#BMPs Rated >= 4	607	378	468	524	290
% of all BMP's rated >=4	92%	89%	89%	89%	87%
Number of score sheets - DNR lands	40	33	40	51	29
Number of score sheets - Private, Other Public lands	22	6	6	11	10

Operations where FRPA inspections occurred:

State operations - Southeast 2025

Bay View (Viking Lumber)
 East Charley (Alcan Timber)
 El Capitan/Whale Pass (Viking Lumber)
 Kaikli Cove (Viking Lumber)
 Parley 3 (Alcan Timber)
 Tuxekan (Alcan Timber)
 Vallenar GNA (Alcan Timber)
 Tsirku Logging Spur (Stump Company)
 Tsirku Logging Spur Ridge (Stump Company)
 KB-24 (Stump Company)
 35 Mile Break North (Dogwood Forest Products)
 Walker Lake South (Stump Company)

State operations - Kenai/Kodiak 2025

n/a

Private & Other Public land operations - Southeast 2025

Alaska Mental Health Trust, Naukati (Viking Lumber)
 Alaska Mental Health Trust, Shelter (Alcan Timber)
 Alaska Mental Health Trust, Leask Lake II (Alcan Timber)
 Alaska Mental Health Trust, Whipple Creek, (Alcan Timber)
 Cape Fox Corporation (Alcan Timber)
 Yak-Tat-Kwaan, Yakutat

Private & Other Public land operations - Kodiak/Afognak 2025

Afognak Native Corporation (SEALogging)



Wind damage, near Naukati on Prince of Wales island (P. Palkovic)

**2025 Compliance Monitoring Summary
Region I**

<u>BMP</u>	<u>Average</u>	<u>#Ratings</u>	<u>BMP</u>	<u>Average</u>	<u>#Ratings</u>		
General			Bridges				
11 AAC 95.815(b) 1x	Disposal of petroleum products	3.8	10	11 AAC 95.300(a)(1)	Install relief culverts on approaches	x	0
11 AAC 95.815(b) 2x	Disposal of scrap metal	4.1	8	11 AAC 95.300(a)(2)	Anchor one end of log bridge	x	0
Riparian Areas			Culverts				
11 AAC 95.265	Classification of surface water bodies	5.0	2	11 AAC 95.300(a)(3)	Protect earth embankment from erosion	x	0
11 AAC 95.280(d)(5)	Sidecasting material in riparian areas	x	0	11 AAC 95.300(a)(4)	Install curbs and filter fabric	x	0
11 AAC 95.285(b)	Locating roads in riparian areas	x	0	11 AAC 95.300(a)(8)	Min. disturbance to bed and bank of stream	x	0
11 AAC 95.350(c)	Leaving high stumps in riparian areas	x	0	11 AAC 95.300(d)	Do not encroach on fish stream	x	0
11 AAC 95.355(e)(1)	Falling trees into retention areas	x	0	Road Maintenance - Active			
11 AAC 95.360(c4)	Cable yarding adjacent to riparian areas	x	0	11 AAC 95.305(a)(3)	Culvert is not perched	4.4	10
11 AAC 95.365(b)	Ground skidding in riparian areas	x	0	11 AAC 95.305(a)(4)	Culvert terminates on non-erodible material	4.7	13
Timber Harvesting			Road Maintenance - Inactive				
11 AAC 95.345 (a)&(b)	Landing location, construction and operation	5.0	21	11 AAC 95.305(a)(7)	Clear of mobile slash	4.2	18
11 AAC 95.350(a)	Min. disturbance adjacent to surface waters	4.1	11	11 AAC 95.305(a)(8)	Catch basins and headwalls	4.4	8
11 AAC 95.350(b)	Avoid disturbing LWD in surface wates	4.3	8	11 AAC 95.305(a)(9)	Culverts are proper length	4.0	17
11 AAC 95.355(c)	Removal of trees from surface waters	4.0	5	Road Maintenance - Active			
11 AAC 95.355(d)	Bucking of trees in surface waters	5.0	2	11 AAC 95.315(b)(1) 1x	Culverts functional	4.2	19
11 AAC 95.360(a)&(b)	Cable yarding adjacent to surface waters	x	0	11 AAC 95.315(b)(1) 2x	Ditches functional	4.1	18
11 AAC 95.360(c)(1-3)	Obtaining deflection when cable yarding	4.3	3	11 AAC 95.315(b)(4) 1x	Roads crowned or outsloped	3.9	18
11 AAC 95.365(f)	Proper skidding techniques followed	4.6	22	11 AAC 95.315(b)(4) 2x	Shoulders free of berms	4.1	17
11 AAC 95.365(g)	Stabilizing & waterbarring skid trails	4.1	14	11 AAC 95.315 (b)(5&6)	Grading bridges	3.7	3
Road Construction			Road Maintenance - Inactive				
11 AAC 95.290(c)	Erosion controls on unstable soils	4.1	9	11 AAC 95.315(c)(2)	Surface not conducive to erosion	5.0	1
11 AAC 95.290(d)	End haul of waste material	4.2	5	11 AAC 95.315(c)(3) 1x	Drainage structures clear	5.0	1
11 AAC 95.290(e)	Fall away from all surface waters	5.0	6	11 AAC 95.315(c)(3) 2x	Ditches clear	4.0	1
11 AAC 95.290(j)	Disposal of material on suitable sites	4.3	12	Road Maintenance - Closed			
Drainage			Road Maintenance - Closed				
11 AAC 95.295(b) 1x	Adequate number of drainage structures	4.6	12	11 AAC 95.320(b)(1)	Road condition suitable to control erosion	5.0	3
11 AAC 95.295(b) 2x	Drainage structures on all natural drainages	4.4	10	11 AAC 95.320(b)(2)	Ditches suuitable to reduce erosion	5.0	2
11 AAC 95.295(d)	Roads outsloped or ditched on uphill side	4.3	16	11 AAC 95.320(b)(4)&(c)	Structure & fills removed from surface waters	4.5	2
11 AAC 95.295(f)	Relief ditches away from surface waters	5.0	1	Combined Average Score			
11 AAC 95.295(i)	Do not discharge onto unprotected slopes	5.0	7	4.3			

X = Not rated in 2025
 Highlight indicates improvement needed

Compliance Monitoring Summary
Previous 5 Years
Region I
2021-2025

BMP						BMP	Average Score				
	2021	2022	2023	2024	2025		2021	2022	2023	2024	2025
General	4.5	4.0	4.2	4.4	4.0	Bridges	4.8	4.4	4.1	4.9	x
11 AAC 95.815(b) 1x	4.5	4.0	4.1	4.2	3.8	11 AAC 95.300(a)(1)	5.0	X	4.5	4.8	x
11 AAC 95.815(b) 2x	4.6	4.0	4.3	4.5	4.1	11 AAC 95.300(a)(2)	5.0	X	4.5	5.0	x
Riparian Areas	4.3	3.6	4.2	4.8	5.0	11 AAC 95.300(a)(3)	4.4	4.0	3.0	4.6	x
11 AAC 95.265	4.3	3.5	4.5	5.0	5.0	11 AAC 95.300(a)(4)	4.4	4.0	4.0	4.7	x
11 AAC 95.280(d)(5)	4.9	4.0	4.5	4.3	x	11 AAC 95.300(a)(8)	4.8	4.7	4.0	5.0	x
11 AAC 95.285(b)	4.0	3.0	3.0	5.0	x	11 AAC 95.300(d)	5.0	4.7	4.5	5.0	x
11 AAC 95.350(c)	4.0	5.0	X	4.7	x	Culverts	4.4	4.6	4.5	4.3	4.3
11 AAC 95.355(e)(1)	4.3	5.0	5.0	5.0	x	11 AAC 95.305(a)(3)	X	5.0	5.0	4.8	4.4
11 AAC 95.360(c)	X	X	X	X	x	11 AAC 95.305(a)(4)	4.6	4.8	4.8	4.2	4.7
11 AAC 95.365(b)	4.1	1.0	4.0	4.5	x	11 AAC 95.305(a)(7)	4.3	4.3	3.9	4.1	4.2
Timber Harvesting	4.5	4.5	4.3	4.4	4.4	11 AAC 95.305(a)(8)	4.2	4.8	4.7	4.3	4.4
11 AAC 95.345 (a)&(b)	4.8	4.9	4.5	4.6	5.0	11 AAC 95.305(a)(9)	4.8	4.1	4.2	4.1	4.0
11 AAC 95.350(a)	4.3	4.0	3.7	4.0	4.1	Road Maintenance -					
11 AAC 95.350(b)	4.3	4.3	3.9	4.3	4.3	Active	4.4	4.2	4.0	4.1	4.0
11 AAC 95.355(c)	4.2	5.0	4.0	4.2	4.0	11 AAC 95.315(b)(1) 1x	4.8	4.0	4.2	4.3	4.2
11 AAC 95.355(d)	4.5	5.0	4.9	5.0	5.0	11 AAC 95.315(b)(1) 2x	4.8	3.9	4.2	3.9	4.1
11 AAC 95.360(a)&(b)	X	X	X	4.3	x	11 AAC 95.315(b)(4) 1x	4.1	4.1	3.7	3.8	3.9
11 AAC 95.360(c)(1-3)	5.0	X	X	4.0	4.3	11 AAC 95.315(b)(4) 2x	4.6	4.2	4.0	4.1	4.1
11 AAC 95.365(f)	4.6	4.5	4.5	4.7	4.6	11 AAC 95.315 (b)(5&6)	3.7	4.6	3.8	4.2	3.7
11 AAC 95.365(g)	4.8	3.9	4.5	4.1	4.1	Road Maintenance -					
Road Construction	4.8	4.3	4.5	4.7	4.4	Inactive	4.1	4.5	4.3	4.2	4.7
11 AAC 95.290(c)	4.5	4.4	4.3	4.2	4.1	11 AAC 95.315(c)(2)	4.0	4.0	5.0	3.8	5.0
11 AAC 95.290(d)	5.0	4.4	4.0	5.0	4.2	11 AAC 95.315(c)(3) 1x	4.0	5.0	3.0	4.7	5.0
11 AAC 95.290(e)	4.7	4.0	4.8	4.7	5.0	11 AAC 95.315(c)(3) 2x	4.3	4.5	5.0	4.2	4.0
11 AAC 95.290(i)	4.9	3.5	5.0	4.7	4.3	Road Maintenance -					
Drainage	4.7	4.5	4.5	4.3	4.7	Closed	X	4.0	4.5	4.7	4.8
11 AAC 95.295(b) 1x	4.4	4.3	4.6	4.4	4.6	11 AAC 95.320(b)(1)	X	4.0	4.5	4.7	5.0
11 AAC 95.295(b) 2x	4.3	4.8	4.4	4.3	4.4	11 AAC 95.320(b)(2)	X	4.0	4.5	4.3	5.0
11 AAC 95.295(d)	4.8	4.2	3.9	4.2	4.3	11 AAC 95.320(b)(4)&(c)	X	4.0	4.5	5.0	4.5
11 AAC 95.295(f)	4.7	4.0	4.7	4.3	5.0	Average Combined					
11 AAC 95.295(i)	5.0	5.0	5.0	4.5	5.0	Scores	4.5	4.3	4.2	4.3	4.3

Highlight indicates improvement needed
X Indicates BMP was not evaluated during this period

FRPA REGION II COMPLIANCE RATINGS AND INSPECTION TOTALS

REGION II Totals	2021	2022	2023	2024	2025
#BMPs Rated	39	0	15	40	14
Average Score all BMPs on a 1 to 5 (best) scale	4.6	X	4.8	4.6	5.0
#BMPs Rated <4	0	X	0	7	0
% of all BMP's rated <4	0.0%	X	0%	18%	0%
#BMPs Rated >= 4	39	X	15	33	14
% of all BMP's rated >=4	100.0%	X	100%	83%	100%
Number of score sheets - DNR lands	9	0	0	0	2
Number of score sheets - Private, Other					
Public lands	0	0	4	5	1

Operations where FRPA inspections occurred:

State operations - Kenai Peninsula 2025

Padra PU (D. Padra)
Kauffman PU (T. Kaufman)

State operations - Mat Su 2025

n/a

Private & Other Public land operations - Kenai Peninsula 2025

n/a

Private & Other Public land operations - Mat Su 2025

Mat-Su Borough (Webster Wood Service)



Feller buncher on borough sale (S.Nickel)

**2025 Compliance Monitoring Summary
Region II**

<u>BMP</u>		<u>Average</u>	<u>#Ratings</u>		<u>BMP</u>		<u>Average</u>	<u>#Ratings</u>
General				Bridges				
11 AAC 95.815(b)	1x Disposal of petroleum products	5.0	2	11 AAC 95.300(a)(1)	Install relief culverts on approaches	X	0	
11 AAC 95.815(b)	2x Disposal of scrap metal	5.0	2	11 AAC 95.300(a)(3)	Protect earth embankment from erosion	X	0	
Riparian Areas				11 AAC 95.300(a)(4)	Install curbs and filter fabric	X	0	
11 AAC 95.280(d)(5)	Sidcasting material in riparian areas	X	0	11 AAC 95.300(a)(5)	Construction of ice bridges	X	0	
11 AAC 95.285(b)	Locating roads in riparian areas	X	0	11 AAC 95.300(a)(8)	Min. disturbance to bed and bank of stream	X	0	
11 AAC 95.355(e)(1)	Falling trees into retention areas	X	0	11 AAC 95.300(d)	Do not encroach on fish stream	X	0	
11 AAC 95.365(b)	Ground skidding in riparian areas	X	0	Culverts				
Timber Harvesting				11 AAC 95.305(a)(3)	Culvert is not perched	X	0	
11 AAC 95.345 (a)&(b)	Landing location, construction and operation	5.0	3	11 AAC 95.305(a)(4)	Culvert terminates on non-erodible material	X	0	
11 AAC 95.350(a)	Min. disturbance adjacent to surface waters	X	0	11 AAC 95.305(a)(7)	Clear of mobile slash	X	0	
11 AAC 95.355(c)	Removal of trees from surface waters	X	0	11 AAC 95.305(a)(8)	Catch basins and headwalls	X	0	
11 AAC 95.355(d)	Bucking of trees in surface waters	X	0	11 AAC 95.305(a)(9)	Culverts are proper length	X	0	
11 AAC 95.365(c)	Remove debris from frozen surface waters	X	0	Road Maintenance - Active				
11 AAC 95.365(f)	Proper skidding techniques followed	5.0	2	11 AAC 95.315(b)(1) 1x	Culverts functional	X	0	
11 AAC 95.365(g)	Stabilizing & waterbarring skid trails	X	0	11 AAC 95.315(b)(1) 2x	Ditches functional	X	0	
Road Construction				11 AAC 95.315(b)(4) 1x	Roads crowned or outsloped	5.0	1	
11 AAC 95.290(c)	Erosion controls on unstable soils	X	0	11 AAC 95.315(b)(4) 2x	Shoulders free of berms	5.0	1	
11 AAC 95.290(d)	End haul of waste material	X	0	11 AAC 95.315 (b)(5&6)	Grading bridges	X	0	
11 AAC 95.290(e)	Fall away from all surface waters	X	0	Road Maintenance - Inactive				
11 AAC 95.290(f)	Winter road construction & WQ	5.0	1	11 AAC 95.315(c)(2)	Surface not conducive to erosion	X	0	
11 AAC 95.290(h)	Winter road construction on public land	5.0	1	11 AAC 95.315(c)(3) 1x	Drainage structures clear	X	0	
11 AAC 95.290(j)	Disposal of material on suitable sites	5.0	1	11 AAC 95.315(c)(3) 2x	Ditches clear	X	0	
Drainage				Road Maintenance - Closed				
11 AAC 95.295(b) 1x	Adequate number of drainage structures	X	0	11 AAC 95.320(b)(1)	Road condition suitable to control erosion	X	0	
11 AAC 95.295(b) 2x	Drainage structures on all natural drainages	X	0	11 AAC 95.320(b)(2)	Ditches suitable to reduce erosion	X	0	
11 AAC 95.295(d)	Roads outsloped or ditched on uphill side	X	0	11 AAC 95.320(b)(4)&(c)	Structure & fills removed from surface waters	X	0	
11 AAC 95.295(f)	Relief ditches away from surface waters	X	0					
11 AAC 95.295(i)	Do not discharge onto unprotected slopes	X	0					

X = Not rated in 2025

Highlight indicates improvement needed

Combined Average Score

5.0

Compliance Monitoring Summary
Previous 5 Years
Region II
2021-2025

BMP	Average Score					BMP	Average Score				
	2021	2022	2023	2024	2025		2021	2022	2023	2024	2025
General	####	####	5.0	5.0	5.0	Bridges	####	####	####	####	####
11 AAC 95.815(b) 1x	X	X	5.0	5.0	5.0	11 AAC 95.300(a)(1)	X	X	X	X	X
11 AAC 95.815(b) 2x	X	X	5.0	5.0	5.0	11 AAC 95.300(a)(3)	X	X	X	X	X
Riparian Areas	####	####	####	####	####	11 AAC 95.300(a)(4)	X	X	X	X	X
11 AAC 95.280(d)(5)	X	X	X	X	X	11 AAC 95.300(a)(5)	X	X	X	X	X
11 AAC 95.285(b)	X	X	X	X	X	11 AAC 95.300(a)(8)	X	X	X	X	X
11 AAC 95.355(e)(1)	X	X	X	X	X	11 AAC 95.300(d)	X	X	X	X	X
11 AAC 95.365(b)	X	X	X	X	X	Culverts	####	####	####	####	####
Timber Harvesting	4.7	####	4.8	4.6	5.0	11 AAC 95.305(a)(3)	X	X	X	X	X
11 AAC 95.345 (a)&(b)	4.4	X	5.0	5.0	5.0	11 AAC 95.305(a)(4)	X	X	X	X	X
11 AAC 95.350(a)	X	X	4.5	4.5	X	11 AAC 95.305(a)(7)	X	X	X	X	X
11 AAC 95.355(c)	X	X	X	4.0	X	11 AAC 95.305(a)(8)	X	X	X	X	X
11 AAC 95.355(d)	X	X	X	X	X	11 AAC 95.305(a)(9)	X	X	X	X	X
11 AAC 95.365(c)	X	X	X	X	X	Road Maintenance -					
11 AAC 95.365(f)	5.0	X	4.8	5.0	5.0	Active	####	####	####	3.8	5.0
11 AAC 95.365(g)	X	X	5.0	X	X	11 AAC 95.315(b)(1) 1x	X	X	X	X	X
Road Construction	4.6	####	####	5.0	5.0	11 AAC 95.315(b)(1) 2x	X	X	X	3.0	X
11 AAC 95.290(c)	X	X	X	X	X	11 AAC 95.315(b)(4) 1x	X	X	X	4.3	5.0
11 AAC 95.290(d)	X	X	X	X	X	11 AAC 95.315(b)(4) 2x	X	X	X	5.0	5.0
11 AAC 95.290(e)	X	X	X	X	X	11 AAC 95.315 (b)(5&6)	X	X	X	3.0	X
11 AAC 95.290(f)	4.4	X	X	5.0	5.0	Road Maintenance -					
11 AAC 95.290(h)	4.8	X	X	5.0	5.0	Inactive	####	####	####	####	####
11 AAC 95.290(i)	X	X	X	5.0	5.0	11 AAC 95.315(c)(2)	X	X	X	X	X
Drainage	4.7	####	4.0	3.9	####	11 AAC 95.315(c)(3) 1x	X	X	X	X	X
11 AAC 95.295(b) 1x	4.7	X	X	X	X	11 AAC 95.315(c)(3) 2x	X	X	X	X	X
11 AAC 95.295(b) 2x	X	X	X	X	X	Road Maintenance -					
11 AAC 95.295(d)	X	X	4.0	3.7	X	Closed	####	####	####	3.0	####
11 AAC 95.295(f)	X	X	X	3.0	X	11 AAC 95.320(b)(1)	X	X	X	X	X
11 AAC 95.295(i)	X	X	X	5.0	X	11 AAC 95.320(b)(2)	X	X	X	X	X
						11 AAC 95.320(b)(4)&(c)	X	X	X	3.0	X
						Average Combined	4.6	0.0	4.8	4.6	5.0
						Scores					

Highlight indicates improvement needed
X Indicates BMP was not evaluated during this period

FRPA REGION III COMPLIANCE RATINGS AND INSPECTION TOTALS

REGION III Totals	2021	2022	2023	2024	2025
#BMPs Rated	359	150	239	319	51
Average Score all BMPs on a 1 to 5 (best) scale	4.6	4.1	4.7	4.5	4.8
#BMPs Rated <4	26	37	14	32	2
% of all BMP's rated <4	7%	25%	6%	10%	4%
#BMPs Rated >= 4	333	113	225	284	49
% of all BMP's rated >=4	93%	75%	94%	89%	96%
Number of scoresheets - State	24	13	25	48	13
Number of scoresheets - Private, Other					
Public	0	0	0	0	0

Operations where FRPA inspections occurred:

State operations - Fairbanks 2025

- Chappelle Negotiated (AK Logfather & Son)
- Christenson Negotiated (Two Far North Logging)
- Halfway Spruce #3 (Small Bunyan)
- Harding Spruce #3 (Northland Wood)
- Jenny M Hill Mixed (Two Far North Logging)
- Little Ag Mixed (Rob Bennett Enterprises)
- Little Ag Mixed #2 (Rob Bennett Enterprises)
- Lincoln Creek Birch #2 (DNA Logworks)
- Nenana Ridge Habitat #3 (Aurora Energy)
- Nenana Spruce #2 (Logging and Milling Assoc)
- Nenana Spruce #3 (Northland Wood)
- Overstreet Neg 2024 (Sunshine Alaska Woodworks)
- Pagh Rd Spruce #2 Re-sale (Fairchild Logging)
- Rowland #4 (Logging and Milling Assoc)
- Yule Neg 2024 (Tall Timber Enterprises)

State operations - Delta 2025

- 100 Mile Fire Salvage (Helkenn)
- Antonin Kuzmin Negotiated 2023 (Tony's Services)
- Fyodor Kuzmin Negotiated 2023 Kuzmin
- Mississippi Salvage #12 Swearingen
- Parker Negotiated 2024 (Wild Alaska Products)
- Pogo Salvage Decks-1(Larry's Apartments)
- Pogo Salvage Decks-2 (Bialik)
- Pogo Salvage Decks-4 (Salinas)
- Pogo Salvage Decks-5 & 6 (D+D Timber)
- Pogo Salvage Decks-7 (Larry's Apartments)
- Pogo Salvage Decks-8 (F/V Highliner)
- Pogo Salvage Decks-12 (Dorshorst)
- Pogo Salvage Decks-13 (Rocket Firewood)
- Pogo Salvage Decks-14 (Firewood Boys)
- Pogo Mile 14 Fire Salvage (Built Different LLC)
- Quartz lake Mixed (Full Moon Farm and Earthworks)
- Rowland #3 (Granite Mountain Alaska Lumber)
- Sergi Kuzmin Negotiated 2024 (F/V Highliner)

State operations - Tok 2025

- Young Neg Timber Sale 10-yr (Young's Timber)

Private & Other Public land - Region III 2025

n/a



White spruce regeneration, Tok area (T. Chaney)

**2025 Compliance Monitoring Summary
Region III**

<u>BMP</u>	<u>Average</u>	<u>#Ratings</u>	<u>BMP</u>	<u>Average</u>	<u>#Ratings</u>			
General			Bridges					
11 AAC 95.815(b) 1x		Disposal of petroleum products	4.5	4	11 AAC 95.300(a)(1)	Install relief culverts on approaches	X	0
11 AAC 95.815(b) 2x		Disposal of scrap metal	4.7	3	11 AAC 95.300(a)(3)	Protect earth embankment from erosion	5.0	1
Riparian Areas					11 AAC 95.300(a)(4)	Install Curbs and Filter fabric	X	0
11 AAC 95.280(d)(5)		Sidecasting material in riparian areas	X	0	11 AAC 95.300(a)(5)	Construction of ice bridges	5.0	3
11 AAC 95.285(b)		Locating roads in riparian areas	5.0	2	11 AAC 95.300(a)(8)	Min. disturbance to bed and bank of stream	5.0	2
11 AAC 95.355(e)(1)		Falling trees into retention areas	X	0	11 AAC 95.300(d)	Do not encroach on fish stream	5.0	1
11 AAC 95.365(b)		Ground skidding in riparian areas	X	0	Culverts			
Timber Harvesting					11 AAC 95.305(a)(3)	Culvert is not perched	X	0
11 AAC 95.345 (a&b)		Landing location, construction and operation	4.9	7	11 AAC 95.305(a)(4)	Culvert terminates on non-erodible material	X	0
11 AAC 95.350(a)		Min. disturbance adjacent to surface waters	X	0	11 AAC 95.305(a)(7)	Clear of mobile slash	X	0
11 AAC 95.355(c)		Removal of trees from surface waters	X	0	11 AAC 95.305(a)(8)	Catch basins and headwalls	X	0
11 AAC 95.355(d)		Bucking of trees in surface waters	X	0	11 AAC 95.305(a)(9)	Culverts are proper length	X	0
11 AAC 95.365(c)		Remove debris from frozen surface waters	X	0	Road Maintenance - Active			
11 AAC 95.365(f)		Proper skidding techniques followed	5.0	6	11 AAC 95.315(b)(1) 1x	Culverts functional	5.0	1
11 AAC 95.365(g)		Stabilizing & waterbarring skid trails	5.0	3	11 AAC 95.315(b)(1) 2x	Ditches functional	5.0	1
Road Construction					11 AAC 95.315(b)(4) 1x	Roads crowned or outsloped	4.0	1
11 AAC 95.290(c)		Erosion controls on unstable soils	X	0	11 AAC 95.315(b)(4) 2x	Shoulders free of berms	4.5	2
11 AAC 95.290(d)		End haul of waste material	4.0	1	11 AAC 95.315 (b)(5&6)	Grading bridges	X	0
11 AAC 95.290(e)		Fall away from all surface waters	X	0	Road Maintenance - Inactive			
11 AAC 95.290(f)		Winter road construction	4.4	5	11 AAC 95.315(c)(2)	Surface not conducive to erosion	X	0
11 AAC 95.290(h)		Winter road construction on public land	4.7	6	11 AAC 95.315(c)(3) 1x	Drainage structures clear	X	0
11 AAC 95.290(i)		Disposal of material on suitable sites	X	0	11 AAC 95.315(c)(3) 2x	Ditches clear	X	0
Drainage					Road Maintenance - Closed			
11 AAC 95.295(b) 1x		Adequate number of drainage structures	5.0	2	11 AAC 95.320(b)(1)	Road condition suitable to control erosion	X	0
11 AAC 95.295(b) 2x		Drainage structures on all natural drainages	X	0	11 AAC 95.320(b)(2)	Ditches suitable to reduce erosion	X	0
11 AAC 95.295(d)		Roads outsloped or ditched on uphill side	X	0	11 AAC 95.320(b)(4)&(c)	Structure & fills removed from surface waters	X	0
11 AAC 95.295(f)		Relief ditches away from surface waters	X	0				
11 AAC 95.295(i)		Do not discharge onto unprotected slopes	X	0				

X = Not rated in 2025
Highlight indicates improvement needed

Combined Average Score 4.8

**Compliance Monitoring Summary
Previous 5 Years
Region III
2021-2025**

BMP	Average Score					BMP	Average Score				
	2021	2022	2023	2024	2025		2021	2022	2023	2024	2025
General	4.5	4.7	4.8	4.3	4.6	Bridges	4.8	5.0	5.0	5.0	5.0
11 AAC 95.815(b) 1x	4.6	4.6	4.7	4.2	4.5	11 AAC 95.300(a)(1)	X	X	X	X	X
11 AAC 95.815(b) 2x	4.4	4.7	4.8	4.4	4.7	11 AAC 95.300(a)(3)	5.0	5.0	X	X	5.0
Riparian Areas	4.8	4.5	4.7	4.5	5.0	11 AAC 95.300(a)(4)	X	5.0	X	X	X
11 AAC 95.280(d)(5)	4.7	5.0	5.0	4.0	X	11 AAC 95.300(a)(5)	4.7	5.0	5.0	5.0	5.0
11 AAC 95.285(b)	4.9	4.8	5.0	4.9	5.0	11 AAC 95.300(a)(8)	4.3	5.0	5.0	5.0	5.0
11 AAC 95.355(e)(1)	4.4	3.8	4.3	4.7	X	11 AAC 95.300(d)	5.0	5.0	5.0	5.0	5.0
11 AAC 95.365(b)	5.0	4.3	4.3	4.5	X	Culverts	5.0	####	5.0	4.8	####
Timber Harvesting	4.6	3.8	4.7	4.8	5.0	11 AAC 95.305(a)(3)	5.0	X	X	5.0	X
11 AAC 95.345 (a&b)	4.7	4.5	4.7	4.8	4.9	11 AAC 95.305(a)(4)	5.0	X	5.0	4.5	X
11 AAC 95.350(a)	4.9	4.6	4.7	4.6	X	11 AAC 95.305(a)(7)	5.0	X	5.0	5.0	X
11 AAC 95.355(c)	4.7	3.0	3.7	4.5	X	11 AAC 95.305(a)(8)	5.0	X	X	X	X
11 AAC 95.355(d)	5.0	2.0	5.0	5.0	X	11 AAC 95.305(a)(9)	5.0	X	5.0	4.8	X
11 AAC 95.365(c)	4.0	3.5	4.7	5.0	X	Road Maintenance -					
11 AAC 95.365(f)	4.9	5.0	4.9	5.0	5.0	Active	4.4	3.3	4.4	3.8	4.6
11 AAC 95.365(g)	4.4	4.0	5.0	4.6	5.0	11 AAC 95.315(b)(1) 1x	5.0	3.0	5.0	4.0	5.0
Road Construction	4.7	4.0	4.5	4.2	4.4	11 AAC 95.315(b)(1) 2x	4.8	2.3	4.0	3.3	5.0
11 AAC 95.290(c)	4.4	4.0	4.5	4.8	X	11 AAC 95.315(b)(4) 1x	4.1	3.8	4.2	3.7	4.0
11 AAC 95.290(d)	4.9	4.0	4.0	X	4.0	11 AAC 95.315(b)(4) 2x	3.9	3.1	4.3	4.2	4.5
11 AAC 95.290(e)	5.0	5.0	4.3	X	X	11 AAC 95.315 (b)(5&6)	X	4.5	X	X	X
11 AAC 95.290(f)	4.7	4.0	4.9	4.5	4.4	Road Maintenance -					
11 AAC 95.290(h)	4.7	4.0	5.0	4.3	4.7	Inactive	4.0	####	5.0	4.5	####
11 AAC 95.290(i)	4.8	3.0	4.0	3.3	X	11 AAC 95.315(c)(2)	4.0	X	5.0	4.5	X
Drainage	4.4	3.7	4.9	4.7	5.0	11 AAC 95.315(c)(3) 1x	4.0	X	X	X	X
11 AAC 95.295(b) 1x	4.1	3.7	5.0	4.8	5.0	11 AAC 95.315(c)(3) 2x	X	X	X	X	X
11 AAC 95.295(b) 2x	4.3	3.4	4.5	4.5	X	Road Maintenance -					
11 AAC 95.295(d)	4.2	3.7	4.8	4.5	X	Closed	4.5	####	5.0	5.0	####
11 AAC 95.295(f)	4.9	3.0	5.0	X	X	11 AAC 95.320(b)(1)	5.0	X	5.0	5.0	X
11 AAC 95.295(i)	4.8	4.8	5.0	5.0	X	11 AAC 95.320(b)(2)	4.0	X	X	X	X
						11 AAC 95.320(b)(4)&(c)	X	X	X	X	X
						Average Combined					
						Scores	4.5	4.1	4.7	4.5	4.5

Highlight indicates improvement needed
X Indicates BMP was not evaluated during this period